CO PATENT

PE 280684.003203

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Application of:)	
KIICHIRO TAKAHASHI, ET AL.		:	Examiner: L. Liang Group Art Unit: 2853
Application No.: 09/891,589)	
Filed: June 27, 2001)	
For:	INK JET RECORDING METHOD, RECORDING APPARATUS AND DATA PROCESSING METHOD) :)	February 10, 2005
U.S. Patent No. 6,805,422 B2) :	Certificate
Issued: October 19, 2004			FEB 1 6 2005 of Correction

The Honorable Commissioner of Patents and Trademarks P.O. Box 1450 Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the

Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent
and Trademark Office mistakes and mistakes which are not the fault of the Patent and Trademark

Office. A Certificate of Correction form, in duplicate, is enclosed.

02/14/2005 AWOHDAF2 00000027 6805422

01 FC:1811

100.00 GP

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction. Any additional fee required by this paper may be charged to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our below-listed address.

Respectfully submitted,

Attorney for Patentees

Scott D. Malpede

Registration No. 32,533

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

SDM\mm

DC_MAIN 187893v1

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,805,422 B2

DATED

October 19, 2004

INVENTOR(S) :

KIICHIRO TAKAHASHI, ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

FOREIGN PATENT DOCUMENTS, "526205 A2" should read --5-26205; and "04366645 A" should read --4-366645 A--.

SHEET 6:

"CARRINGE" should read -- CARRIAGE ---.

SHEET 20:

"DETERIME" should read -- DETERMINE --.

<u>SHEET 21</u>:

"ETECTION" should read --EJECTION--.

COLUMN 2:

Line 36, "being" should read --ink--.

COLUMN 3:

Line 23, "in" should read --ink--.

COLUMN 5:

Line 24, "areas" should read --area--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,805,422 B2

No. of add'l. copies @ 30¢ per page

 \Rightarrow

Form PTO 1050 (Rev. 3-82) (Form#30)

FEB 1 7 2005

Stable Here Ould Here STRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,805,422 B2

DATED

October 19, 2004

INVENTOR(S) :

KIICHIRO TAKAHASHI, ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 5, "bite" should read --byte--.

Line 16, "graph." should read --graph can be reduced.--.

COLUMN 8:

Line 20, "Details" should read --details-- and "is" should be deleted.

Line 29, "25" should be deleted.

Line 43, "2 the carriage 2" should read --2, which--.

COLUMN 10:

Line 58, "in" should read --if--.

Line 60, "account." should read --account).--.

COLUMN 11:

Line 13, "corporations" should read --operations--.

COLUMN 13:

Line 12, "objections" should read --ejections--.

COLUMN 14:

Line 21, "decrees" should read --degrees--.

Line 61, "direction) since" should read --direction). Since--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,805,422 B2

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l, copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) (Form#30)

Stable Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,805,422 B2

DATED

October 19, 2004

INVENTOR(S) :

KIICHIRO TAKAHASHI, ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 45, "is=2.5), and" should read --is 2.5);--

DC_MAIN 187891v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>6,805,422 B2</u>

No. of add'l. copies

le .

Form PTO 1050 (Rev. 3-82) (Form#30)

FEB 1 7 2005

@ 30¢ per page

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,805,422 B2

DATED

October 19, 2004

INVENTOR(S) :

KIICHIRO TAKAHASHI, ET AL.

Page 1 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

FOREIGN PATENT DOCUMENTS, "526205 A2" should read --5-26205; and "04366645 A" should read --4-366645 A--.

SHEET 6:

"CARRINGE" should read -- CARRIAGE ---.

SHEET 20:

"DETERIME" should read -- DETERMINE --.

SHEET 21:

"ETECTION" should read --EJECTION--.

COLUMN 2:

Line 36, "being" should read --ink--.

COLUMN 3:

Line 23, "in" should read --ink--.

COLUMN 5:

Line 24, "areas" should read --area--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,805,422 B2

No. of add'l. copies @ 30¢ per page

 \Rightarrow

Form PTO 1050 (Rev. 3-82) (Form#30)

FEB 1 7 2005

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,805,422 B2

DATED

October 19, 2004

INVENTOR(S) :

KIICHIRO TAKAHASHI, ET AL.

Page 2 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 7:

Line 5, "bite" should read --byte--.

Line 16, "graph." should read --graph can be reduced.--.

COLUMN 8:

Line 20, "Details" should read --details-- and "is" should be deleted.

Line 29, "25" should be deleted.

Line 43, "2 the carriage 2" should read --2, which--.

COLUMN 10:

Line 58, "in" should read --if--.

Line 60, "account." should read --account).--.

COLUMN 11:

Line 13, "corporations" should read -- operations--.

COLUMN 13:

Line 12, "objections" should read --ejections--.

COLUMN 14:

Line 21, "decrees" should read --degrees--.

Line 61, "direction) since" should read --direction). Since--.

MAILING ADDRESS OF SENDER:

PATENT NO. <u>6,805,422 B2</u>

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801

(212) 219 2100 T 1 1

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

No. of add'l. copies @ 30¢ per page

TEB 1 7 2005

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,805,422 B2

DATED

October 19, 2004

INVENTOR(S) :

KIICHIRO TAKAHASHI, ET AL.

Page 3 of 3

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 20:

Line 45, "is=2.5), and" should read --is 2.5);--

DC_MAIN 187891v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>6,805,422 B2</u>

No. of add'l. copies @ 30¢ per page

 \Rightarrow

Form PTO 1050 (Rev. 3-82) (Form#30)